

Message

---

**From:** Wyatt, John M. [JMWyatt@colpipe.com]  
**Sent:** 4/19/2019 7:10:01 PM  
**To:** Spurlin, Steve [Spurlin.Steve@epa.gov]; todd.taylor@tetrattech.com  
**CC:** Glaze, Gregory [GGlaze@colpipe.com]; Cazares, Juan [JCazares@colpipe.com]  
**Subject:** Colonial Nashville Airport Update 4/19  
**Attachments:** Colonial Nashville Airport 041919.pdf

Steve,

We continue to recover out of both trenches above the creek. 3 dams have been installed at the seep area to prevent a majority of the product from reaching the creek. However, there are still occasional drops of sheen observed in the creek at the southernmost end of the seep.

Attached is the map updated interceptor trench 5. If you have any questions, let me know.

Thanks,

---

**John M. Wyatt**  
Environmental Program Manager  
Southeast District  
  
Colonial Pipeline Company  
4295 Cromwell Rd. #311  
Chattanooga, TN 37421  
Ph: 423-713-7568  
Fax: 770-754-8119

---

---

Colonial Pipeline Notice - This e-mail message (including any attachment) contains information that may be confidential, be protected by attorney-client or other privilege, or constitute non-public information. If you are not the intended recipient, please notify the sender by electronic mail or telephone and delete the original message without making any copies. Use, dissemination, distribution, or reproduction of this message by unintended recipients is not authorized and may be unlawful.